


**Inspection Photos**  
**Divide Road Water Facility**  
**Location ID: #432790 & Facility ID: #432214**  
**Inspection Date: February 20, 2020**



**Photo #1 – Google Earth Aerial of Facility ID #432214 dated 6/17/2016, color-coded to correspond to areas referenced in this Inspection Report.**

**Photo #2 – View of **bullet separators** from southwest.**

**Bullet separators, power generation, water storage tanks, pump building, DAF building, condensate tank battery.**



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**  
Department of Natural Resources

**Inspection Photos**  
**Divide Road Water Facility**  
**Location ID: #432790 & Facility ID: #432214**  
**Inspection Date: February 20, 2020**



**Photo #3 – Tank battery on north side of power generation building contained motor oil and engine coolant tanks inside of cement secondary containment device with loadout containment devices.**



**Photo #4 – ECD and unused equipment stored in northeast corner of facility.**



**Inspection Photos**  
**Divide Road Water Facility**  
**Location ID: #432790 & Facility ID: #432214**  
**Inspection Date: February 20, 2020**



Photo #5 – View into the **power generation** building, from south. No accumulations of E&P waste were observed inside of this building during inspection.



Photo #6 – View of **water storage tanks** inside of lined, fenced secondary containment, from north. Presence of snow on liner prevented closer inspection for liner integrity on inspection date.



**Inspection Photos**  
**Divide Road Water Facility**  
**Location ID: #432790 & Facility ID: #432214**  
**Inspection Date: February 20, 2020**



**Photo #7 – View of equipment inside of pump building. No accumulations of E&P waste were observed inside of this building during inspection.**



**Photo #8 – View of equipment inside of DAF building. No accumulations of E&P waste were observed inside of this building during inspection.**

**Inspection Photos**  
**Divide Road Water Facility**  
**Location ID: #432790 & Facility ID: #432214**  
**Inspection Date: February 20, 2020**



**Photo #9 - View of equipment inside of DAF building. No accumulations of E&P waste were observed inside of this building during inspection.**



**Photo #10 - View of equipment inside of DAF building. No accumulations of E&P waste were observed inside of this building during inspection.**

**Inspection Photos**  
**Divide Road Water Facility**  
**Location ID: #432790 & Facility ID: #432214**  
**Inspection Date: February 20, 2020**



**Photo #11 – View of condensate tank battery from southwest.**



**Photo #12 - View of condensate tank battery from east, looking southwest.**





**Inspection Photos**  
**Divide Road Water Facility**  
**Location ID: #432790 & Facility ID: #432214**  
**Inspection Date: February 20, 2020**



**Photo #13 - View of condensate tank battery from east, looking northwest.**