

Inspection Photos
Location Name: Pronghorn 31-34-6HZ
Location ID: 427009



Photo 1 – Pumping Unit



Photo 2 – Tank Battery



Inspection Photos
Location Name: Pronghorn 31-34-6HZ
Location ID: 427009




Photo 3 – Stained Soil at Wellhead



Photo 4 – Stained Soil at Wellhead



Inspection Photos
Location Name: Pronghorn 31-34-6HZ
Location ID: 427009



Photo 5 – Stained Soil at SE Tank inside Berm