

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2019

Submitted Date:

07/19/2019

Document Number:

696600357**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 312707      Wentzel, Dougo      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER      State: CO      Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, DNR		dnr_cogccengineering@state.co.us	All Engineering
Clark, Chris		cogccnotifications@laramie-energy.com	All Inspections
, DNR		dnr_cogccengineering@state.co.us	All Engineering
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275664	WELL	SI	04/01/2019	GW	077-08850	CURRIER 1-13 (BK1)	TA
451934	WELL	PA	05/12/2018		077-10465	SCU 0993-01-07E	PA

**General Comment:**

This is a follow up from inspection dated 4/22/2019 Doc# 675002206 Required Corrective Action (s) items noted in previous inspections have been satisfied.

Well head removed and set to the side

Tank battery and separator have been removed from location.

4 frac tanks and 2 pumps remain on location in containment.

All storm water corrections from previous inspection have been completed

Form 33 doc#402108067 for injection well permit filed 7/17/19

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	At Entrance of location		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Other	# 4		corrective date
Comment:	Frac tanks in containment		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well head with plunger lift set of to side of well		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Pumps		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

**Inspected Facilities**Facility ID: 275664 Type: WELL API Number: 077-08850 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: [Temporarily Abandoned.](#)  
[Form 33 doc#402108067 for injection well permit filed 7/17/19](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 451934 Type: WELL API Number: 077-10465 Status: PA Insp. Status: PA

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
		Gravel	Pass			
Berms	Pass					
Drains	Pass					
		Drains	Pass			
Compaction	Pass					
Check Dams	Pass					
Waddles	Pass					
Gravel	Pass					
		Compaction	Pass			
		Culverts	Pass			
Culverts	Pass					

Comment: At time of inspection stormwater erosion appears to be controlled.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On (Friday) (7/19/19) at approximately (1153),  I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Re-Inspection)  at (Laramie) (Currier 1-13 (BK1)), (API #077-08850) in (Mesa) Colorado.  During this inspection no compliance issues were observed:  Well is TA and production equipment has been removed from location.  Form 33, doc#402108067 for injection well permit filed 7/17/19  Corrective actions from previous inspection have been made:  This is a summary of inspection report.</p>	wentzeld	07/19/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696600358	Inspection 696600357 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885378">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4885378</a>