

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/25/2020

Submitted Date:

02/25/2020

Document Number:

700700174

FIELD INSPECTION FORM

 Loc ID 383321 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10531
 Name of Operator: GRIZZLY OPERATING LLC
 Address: 5847 SAN FELIPE #3000
 City: HOUSTON State: TX Zip: 77057
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 19 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		scollett@grizzlyenergyllc.com	
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S
, Grizzly		aaxelson@grizzlyenergyllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300520	WELL	PR	12/31/2009	GW	045-17925	GGU MILLER 14A-32-691	PR
300521	WELL	PR	11/30/2009	GW	045-17926	GGU MILLER 43A-31-691	PR
300522	WELL	PR	11/30/2009	GW	045-17927	GGU MILLER 44C-31-691	PR
300523	WELL	PR	11/30/2009	GW	045-17928	GGU MILLER 44A-31-691	PR
300524	WELL	PR	12/29/2009	GW	045-17929	GGU MILLER 14B-32-691	PR
300525	WELL	PR	12/19/2009	GW	045-17930	GGU MILLER 14C-32-691	PR
300526	WELL	PR	07/26/2010	GW	045-17931	GGU MILLER 14D-32-691	PR
300527	WELL	PR	11/25/2009	GW	045-17932	GGU MILLER 44D-31-691	PR
300528	WELL	PR	11/07/2009	GW	045-17933	MILLER 43B-6-791	PR
300529	WELL	PR	11/07/2009	GW	045-17934	MILLER 43D-6-791	PR
300530	WELL	PR	11/03/2009	GW	045-17935	MILLER 43C-6-791	PR
300531	WELL	PR	11/07/2009	GW	045-17936	MILLER 43A-6-791	PR

General Comment:

COGCC Inspection Report Summary

On Tuesday 2/25/20 at approximately 2:00 PM, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Miller 7, at Location # 383321 in Garfield Colorado.

While there, I observed normal production operations. All C/A(s) from previous inspection document # 689303186 have been satisfied. This is a summary of inspection report.

Location

Lease Road:			
	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
	Type BATTERY		
Comment:			
Corrective Action:			Date:
	Type CONTAINERS		
Comment:			
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: 911		
Corrective Action:			Date: _____

Good Housekeeping:			
	Type DEBRIS		
Comment:			
Corrective Action:			Date:
	Type STORAGE OF SUPL		
Comment:			
Corrective Action:			Date:
	Type UNUSED EQUIPMENT		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:				corrective date
Type: Bird Protectors	# 10			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 12			
Comment:				
Corrective Action:				Date:
Type: Pig Station	# 1			
Comment:				
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 2			
Comment:	chemical tanks			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 12			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	8	500 BBLs	STEEL AST		,
Comment:	Three tanks are heated				
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	YES				
Comment:	Three braden heads are open to a tank 045-17933 045-17936 045-17935				
Corrective Action:					Date:
Flaring:					
Type	Ignitor/Combustor				
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	300520	Type:	WELL	API Number:	045-17925	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300521	Type:	WELL	API Number:	045-17926	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300522	Type:	WELL	API Number:	045-17927	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300523	Type:	WELL	API Number:	045-17928	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300524	Type:	WELL	API Number:	045-17929	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300525	Type:	WELL	API Number:	045-17930	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300526	Type:	WELL	API Number:	045-17931	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	300527	Type:	WELL	API Number:	045-17932	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Facility ID: <u>300528</u>	Type: <u>WELL</u>	API Number: <u>045-17933</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	<u>producing</u>			
Corrective Action:			Date:	
Facility ID: <u>300529</u>	Type: <u>WELL</u>	API Number: <u>045-17934</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	<u>producing</u>			
Corrective Action:			Date:	
Facility ID: <u>300530</u>	Type: <u>WELL</u>	API Number: <u>045-17935</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	<u>producing</u>			
Corrective Action:			Date:	
Facility ID: <u>300531</u>	Type: <u>WELL</u>	API Number: <u>045-17936</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment:	<u>producing</u>			
Corrective Action:			Date:	

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Berms		Ditches				

Comment: [limited storm water inspection due to snow](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700178	Photos for Miller 7	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5077658