

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/25/2020

Submitted Date:

02/25/2020

Document Number:

700700175**FIELD INSPECTION FORM**Loc ID 423439 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Grizzly		scollett@grizzlyenergyllc.com	
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412841	WELL	PR	07/21/2011	GW	045-18667	MILLER 33D-6-791	PR
412843	WELL	PR	07/21/2011	GW	045-18666	MILLER 33C-6-791	PR
412844	WELL	PR	06/06/2011	GW	045-18665	MILLER 33B-6-791	PR
412845	WELL	PR	09/01/2019	GW	045-18664	MILLER 33A-6-791	PR
412846	WELL	PR	07/21/2011	GW	045-18663	MILLER FEDERAL 23D-6-791	PR
412847	WELL	PR	06/06/2011	GW	045-18662	MILLER FEDERAL 23C-6-791	PR
412848	WELL	PR	06/06/2011	GW	045-18661	MILLER FEDERAL 23B-6-791	PR
412849	WELL	PR	07/20/2011	GW	045-18660	MILLER FEDERAL 24D-31-691	PR
412850	WELL	PR	07/20/2011	GW	045-18659	MILLER FEDERAL 24C-31-691	PR
412853	WELL	PR	07/01/2019	GW	045-18657	MILLER FEDERAL 24A-31-691	PR
412910	WELL	PR	07/21/2011	GW	045-18658	MILLER FEDERAL 24B 31-691	PR

General Comment:

COGCC Inspection Report Summary

On Tuesday 2/25/20 at approximately 2:30 PM, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Miller 10, at Location # 423439 in Garfield Colorado.

While there, I observed normal production operations. Frack tank on location is being hauled off this week and is empty according to Production forman.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Frack tank has proper labeling but is being hauled off this week.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:			
Corrective Action:		Date:	
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Type	STORAGE OF SUPL		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Type	SEPARATOR			
Comment:				
Corrective Action:			Date:	

Equipment:			corrective date
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	chemical tanks at well heads		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	#		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 11		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:	All braden heads are closed		
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	412841	Type:	WELL	API Number:	045-18667	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	412843	Type:	WELL	API Number:	045-18666	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	412844	Type:	WELL	API Number:	045-18665	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	412845	Type:	WELL	API Number:	045-18664	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	412846	Type:	WELL	API Number:	045-18663	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	412847	Type:	WELL	API Number:	045-18662	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	412848	Type:	WELL	API Number:	045-18661	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	412849	Type:	WELL	API Number:	045-18660	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	412850	Type:	WELL	API Number:	045-18659	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	412853	Type:	WELL	API Number:	045-18657	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	412910	Type:	WELL	API Number:	045-18658	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches		Ditches				
Berms		Culverts				

Comment: [Limited stormwater inspection due to snow](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700179	Photos for Miller 10	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5077659