

**Inspection Photos**  
**Location Name: YB-1**  
**API: 05-083-06252**



**YB-1 well head and flow line.**



**Salt stained area to the SW of the well head.**

**Inspection Photos**  
**Location Name: YB-1**  
**API: 05-083-06252**



**Salt crusted soil and erosion along SW corner of location.**



**Salt crusted storm water flow pattern along the SW corner of the location.**