

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/20/2020

Submitted Date:

02/26/2020

Document Number:

688800682

FIELD INSPECTION FORM

Loc ID 313480 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46685
Name of Operator: KINDER MORGAN CO2 CO LP
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Jardine, Jennifer		jjardine@blm.gov	
Fischer, Alex		alex.fischer@state.co.us	
Hannigan, Michael	(970) 882-5532	CO2Source_Regulatory@kindermorgan.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224187	WELL	PR	03/07/2018	GW	083-06252	MCELMO DOME UNIT 23-13-18 YB #1	EI

General Comment:

On February 20, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan YB-1. For the most recent field inspection report of this facility, please refer to document #685301790.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Location sign posted near entrance.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 224187 Type: WELL API Number: 083-06252 Status: PR Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: _____

Comment: Potential historical release suspected in an area SW of well head. Area is salt stained hard pan that is devoid of vegetation.

Corrective Action: Contact COGCC EPS staff regarding Rule 906.c. Date: 02/28/2020

Reportable: _____ GPS: Lat 37.445074 Long -108.807353

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p style="color: blue; font-size: small;">On February 20, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Kinder Morgan YB-1. For the most recent field inspection report of this facility, please refer to document #685301790.</p> <p style="color: blue; font-size: small;">An area to the southwest of the well head is devoid of vegetation and is salt stained. This area is located approximately at 37.445074/-108.807353. The operator shall investigate this area for a potential historical release. Aerial imagery indicate that this area historically will not support plant life.</p>	hughesjo	02/26/2020

Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800683	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5077991