

Inspection Photos
Location Name: YB-3
API: 05-083-06375



YB Cluster CDP and tank battery.



YB-3 well head and flow line.

Inspection Photos
Location Name: YB-3
API: 05-083-06375



Staining below flow line vents from lubricant used during installation of internal sleeve.



Lubricant weeping out of flow line vents.