

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/26/2020

Submitted Date:

02/26/2020

Document Number:

697000637

**FIELD INSPECTION FORM**

Loc ID 307064 Inspector Name: Peterson, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10312  
Name of Operator: PROSPECT ENERGY LLC  
Address: 1036 COUNTRY CLUB ESTATES DR  
City: CASTLE ROCK State: CO Zip: 80108

**Findings:**

4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Gracey, Cameron		graceyservices@msn.com	
Giltner, Ward		wgiltner@yahoo.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216722	WELL	PR	03/30/1994	OW	069-05135	SABIN (MUDDY UNIT) 1	PR

**General Comment:**

*(This area is currently blank for general comments.)*

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Chain link		
Corrective Action:		Date:	

**Equipment:**

Type	Area	Volume	corrective date
Type: Flow Line		# 1	
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked		# 2	
Comment:			
Corrective Action:		Date:	
Type: Prime Mover		# 1	
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Bradenhead		# 1	
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	
Type: Pump Jack		# 1	
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 216722 Type: WELL API Number: 069-05135 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697000638	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5078965">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5078965</a>