



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	Adequate	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	DEBRIS		
Comment:	dead weeds		
Corrective Action:	Location is within a designated setback location, remove trash or debris per Rule 604.c. (2)P. See attached photo #.3		Date: <u>03/16/2020</u>

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Bradenhead	# 1		
Comment:	Appers to be plumbed to surface		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		

Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	FIBERGLASS AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	crushed asphalt			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		39.867699,-104.534829
Comment:	Tanks that are not adequately painted				
Corrective Action:	Per Rule 804. See attached photo #.1				Date: 08/17/2020

**Paint**

Condition	Inadequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	crushed asphalt			
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:				Date:

**Flaring:**

Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 203566 Type: WELL API Number: 001-09126 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Thursday February 20th 2020 at approximately 10:15am, I, Inspector Chane Finkenbinder,                      Conducted an on-site inspection at the Ambush #31-22, Painted Pegasus Petroleum, at API # 001-09126 in Adams County Colorado.                      While there, I observed a shut in well. During this inspection the following possible compliance issues were observed:                      Debris / dead weeds on location. Location is within a designated setback location, remove trash or debris per Rule 604.c.(2)P. Corrective Action Date 3/16/2020 See attached photo #.3                      Tanks that are not adequately panted per Rule 804. Corrective Action Date 8/17/2020 See attached photo #.1                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	finkenbc	02/20/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402318786	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5072994">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5072994</a>
700900040	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5072993">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5072993</a>