



**Location**

Overall Good:

**Signs/Marker:**

|                    |          |  |       |
|--------------------|----------|--|-------|
| Type               | WELLHEAD |  |       |
| Comment:           |          |  |       |
| Corrective Action: |          |  | Date: |

**Emergency Contact Number:**

|                    |  |  |             |
|--------------------|--|--|-------------|
| Comment:           |  |  |             |
| Corrective Action: |  |  | Date: _____ |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

|                    |          |  |       |
|--------------------|----------|--|-------|
| Type               | WELLHEAD |  |       |
| Comment:           |          |  |       |
| Corrective Action: |          |  | Date: |

**Equipment:**

|                    |     |  |                 |
|--------------------|-----|--|-----------------|
|                    |     |  | corrective date |
| Type: Plunger Lift | # 1 |  |                 |
| Comment:           |     |  |                 |
| Corrective Action: |     |  | Date:           |

**Tanks and Berms:**

| Contents           | #                               | Capacity | Type                | Tank ID | SE GPS |
|--------------------|---------------------------------|----------|---------------------|---------|--------|
|                    |                                 |          | CENTRALIZED BATTERY |         | ,      |
| Comment:           | Battery location number: 328406 |          |                     |         |        |
| Corrective Action: |                                 |          |                     |         | Date:  |

**Paint**

|                  |  |  |  |
|------------------|--|--|--|
| Condition        |  |  |  |
| Other (Content)  |  |  |  |
| Other (Capacity) |  |  |  |
| Other (Type)     |  |  |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 248154 Type: WELL API Number: 123-15952 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

| Comment                                      | User     | Date       |
|--|----------|------------|
| <a href="#">Routine wellhead inspection.</a> | carlilec | 02/27/2020 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 690005124    | Photo       | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5079824">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5079824</a> |