

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/26/2020

Submitted Date:

02/27/2020

Document Number:

689704273

FIELD INSPECTION FORM

Loc ID 335088 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211064	WELL	PR	01/26/2015	GW	045-06822	CHEVRON MV 55-29	PR
260718	WELL	PR	11/19/2001	GW	045-07903	CHEVRON GM 22-29	PR
282720	WELL	PR	03/18/2006	GW	045-11803	CHEVRON GM 421-29	PR
282721	WELL	PR	04/11/2006	GW	045-11802	CHEVRON GM 321-29	PR

General Comment:

This is a summary of inspection report.
On Wednesday 02/26/2020 at approximately 1120 hours, I, Inspector Mike Longworth, conducted a field inspection at Terra Rocky Mountain LLC CHEVRON-66S96W 29NENW, at Location # 335088 in Garfield County, Colorado
During this inspection the following possible compliance issues were observed:
Top of produced water tank is rusted out.
Inspect, maintain and repair tanks following standard industry practice such as API 12R.
C.A. Date 03/31/2020
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	_____
Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		
Comment:	Top of produced water tank is rusted out.				
Corrective Action:	Inspect, maintain and repair tanks following standard industry practice such as API 12R.				Date: 03/31/2020

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>211064</u>	Type:	<u>WELL</u>	API Number:	<u>045-06822</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>								
Corrective Action:								Date:	
Facility ID:	<u>260718</u>	Type:	<u>WELL</u>	API Number:	<u>045-07903</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>								
Corrective Action:								Date:	
Facility ID:	<u>282720</u>	Type:	<u>WELL</u>	API Number:	<u>045-11803</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>								
Corrective Action:								Date:	
Facility ID:	<u>282721</u>	Type:	<u>WELL</u>	API Number:	<u>045-11802</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					
		Gravel	Pass			
		Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704275	Inspection 689704273 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5080070