

Inspection Photos
Operator: Hilcorp Energy
Location #: 067-08075
Date: 2/27/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern project area facing eastward. Vegetation in reclamation area is approximately the same as surrounding irrigated field.



Photo 3. View of the western project area from the northwestern project area facing southward. Vegetation in reclamation area is approximately the same as surrounding irrigated field.



Photo 4. View of what appears to be release with discolored soil flowing toward southeast. Orange fencing surrounds an excavation area.



Photo 5. View of facilities in the southeastern project area. Lighter colored soil in flow pattern toward facilities and beyond, appears to be from release.



Photo 6. View of guyline anchor at well pad entrance where marker is no longer functioning, needs to be marked or removed.



Photo 7. View of the reference area, comprised of irrigated field in dormant vegetative condition.