

Inspection Photos

Location Name: DROP OUT 24-8 CA DATE 3-13-20

API#: 05-071-08831

INSP. #: 695102225



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos

Location Name: DROP OUT 24-8 CA DATE 3-13-20

API#: 05-071-08831

INSP. #: 695102225



PHOTO 3: ACCORDING TO RECORDS POSTED IN METER HOUSE THIS METER HAS NOT BEEN CALIBRATED SINCE MARCH OF 2018 (ALTHOUGH THIS IS NOT A POINT OF SALES METER THE RULE WILL BE CHANGING AND AFTER JULY 1 OF THIS YEAR THIS WOULD BE A VIOLATION).

**PHOTO 4: NO FREEBOARD MARKER INSTALLED ON PIT.
INSTALL FREEBOARD MARKER IN ACCORDANCE WITH 902.b.
CA DATE 3-13-20.**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

INSP. #: 695102225



Colorado Oil & Gas Conservation Commission
37.17989, -104.80418, 2132.0m, 2°
2020/02/27 16:01:57



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: DROP OUT 24-8 CA DATE 3-13-20

API#: 05-071-08831

INSP. #: 695102225



Colorado Oil & Gas Conservation Commission
37.17977, -104.8043, 2133.0m, 15°
2020/02/27 15:55:33

PHOTO 5: APPEARS THAT HYDRAULIC CONNECTIONS ARE LEAKING. REPAIR LEAKS ON ALL EQUIPMENT AND MAINTAIN ALL EQUIPMENT TO PREVENT LEAKS AND SOIL CONTAMINATION, Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. CA DATE 3-13-20



Colorado Oil & Gas Conservation Commission
37.17981, -104.80422, 2130.0m, 36°
2020/02/27 15:56:45

PHOTO 6: LEAKS ON PUMPJACK GEARBOX. REPAIR LEAKS ON ALL EQUIPMENT AND MAINTAIN ALL EQUIPMENT TO PREVENT LEAKS AND SOIL CONTAMINATION, Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. CA DATE 3-13-20

Inspection Photos

Location Name: DROP OUT 24-8 CA DATE 3-13-20

API#: 05-071-08831

INSP. #: 695102225



Colorado Oil & Gas Conservation Commission
37.17988, -104.80425, 2128.0m, 300°
2020/02/27 15:58:00

PHOTO 7: APPEARS THAT HYDRAULIC MOTOR ON COMPRESSOR IS LEAKING. REPAIR LEAKS ON ALL EQUIPMENT AND MAINTAIN ALL EQUIPMENT TO PREVENT LEAKS AND SOIL CONTAMINATION, Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. CA DATE 3-13-20



Colorado Oil & Gas Conservation Commission
37.17989, -104.80433, 2127.0m, 30°
2020/02/27 15:58:53

PHOTO 8: MOTOR ON COMPRESSOR ENGINE SKID IS LEAKING IN MULTIPLE SPOTS. REPAIR LEAKS ON ALL EQUIPMENT AND MAINTAIN ALL EQUIPMENT TO PREVENT LEAKS AND SOIL CONTAMINATION, Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. CA DATE 3-13-20



Inspection Photos

Location Name: DROP OUT 24-8 CA DATE 3-13-20

API#: 05-071-08831

INSP. #: 695102225



PHOTO 9: SOIL APPEARS TO BE CONTAMINATED FROM LEAKING HYDRALIC OIL. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 3-3-20.



PHOTO 10: IMPACTED SOIL STARTING FROM PUMPJACK PAD AROUND WELLHEAD. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 3-3-20.

Inspection Photos

Location Name: DROP OUT 24-8 CA DATE 3-13-20

API#: 05-071-08831

INSP. #: 695102225



PHOTO 11: IMPACTED SOIL ALL AROUND AND UNDER COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 3-3-20.



PHOTO 12: IMPACTED SOIL NEAR SOUND WALLS BETWEEN COMPRESSOR SKID AND SOUND WALL. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 3-3-20.

Inspection Photos

Location Name: DROP OUT 24-8 CA DATE 3-13-20

API#: 05-071-08831

INSP. #: 695102225



Colorado Oil & Gas Conservation Commission
37.17989, -104.80438, 2126.0m, 131°
2020/02/27 15:58:38



Colorado Oil & Gas Conservation Commission
37.17989, -104.80433, 2126.0m, 62°
2020/02/27 15:58:49

PHOTO 13: IMPACTED SOIL NEXT TO PUMPJACK PAD NEAR SOUND WALL. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 3-3-20.

PHOTO 14: IMPACTED SOIL NEAR PRIME MOVER INSIDE SOUND WALLS. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 3-3-20.

Inspection Photos

Location Name: DROP OUT 24-8 CA DATE 3-13-20

API#: 05-071-08831

INSP. #: 695102225



Colorado Oil & Gas Conservation Commission
37.17973, -104.80424, 2134.0m, 95°
2020/02/27 16:04:07

PHOTO 15: IMPACTED SOIL NEXT METER HOUSE.

Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 3-3-20.



Colorado Oil & Gas Conservation Commission
37.17989, -104.80433, 2127.0m, 250°
2020/02/27 15:59:30

PHOTO 16: OILY WASTE INSIDE PRIME MOVER

SKID. Comply with general provisions of the oil and gas act for wildlife protection. CA DATE 3-13-20.