

Grand Mesa Operating CO, Dado 2-21
073-06770


Inspection #688306990

2/27/2020

Surface Cementing Inspection



Colorado Oil and Gas Conservation Commission
39.42834, -103.5502, 5416.7ft, 222°
02/27/2020 10:56:01 AM



Colorado Oil and Gas Conservation Commission
39.43003, -103.55322, 5413.4ft, 112°
02/27/2020 08:15:53 AM



Colorado Oil and Gas Conservation Commission

39.43026, -103.55279, 5413.4ft, 213°

02/27/2020 08:14:45 AM



Colorado Oil and Gas Conservation Commission
39.43, -103.55307, 5403.5ft, 222°
02/27/2020 08:14:05 AM




Colorado Oil and Gas Conservation Commission
39.43028, -103.55278, 5416.7ft, 43°
02/27/2020 08:14:37 AM



Colorado Oil and Gas Conservation Commission
39.43023, -103.5528, 5410.1ft, 107°
02/27/2020 08:14:56 AM



Colorado Oil and Gas Conservation Commission
39.42982, -103.55295, 5400.3ft, 70°
02/27/2020 08:17:46 AM



Cut into bedrock
on SE corner of
location.

Colorado Oil and Gas Conservation Commission
39.42952, -103.55272, 5367.5ft, 102°
02/27/2020 10:12:00 AM



Colorado Oil and Gas Conservation Commission
39.42951, -103.5527, 5380.6ft, 131°
02/27/2020 10:12:03 AM