

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/28/2020

Submitted Date:

02/28/2020

Document Number:

700400251

**FIELD INSPECTION FORM**

Loc ID 315316 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 16700  
Name of Operator: CHEVRON USA INC  
Address: 100 CHEVRON ROAD  
City: RANGELY State: CO Zip: 81648

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Sanford, Anita		atlx@chevron.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230624	WELL	PR	02/01/2018	OW	103-08292	MCLAUGHLIN A. C. #68X	PR

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 2-28-2020 at approximately 15:15, inspector Rick Moran, conducted a routine inspection at Chevron well A.C. McLaughlin 68X in Rio Blanco county.

The following compliance issues were observed:

- 1) Unused cable trash. Photo 2. Complete by 3-28-2020.
- 2) Missing "911" on well head sign. Photo 3. Complete by 3-28-2020.

A follow up inspection will occur to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 700400251.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Missing "911" on well head sign.	Date:	03/28/2020
Corrective Action:	Install sign to comply with Rule 210.b.		

**Good Housekeeping:**

Type	TRASH		
Comment:	Unused 6' of subpump cable next to well head.		
Corrective Action:	Comply with Rule 603.f .	Date:	03/28/2020

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type:			corrective date
Ancillary equipment	# 2		
Comment:	Containers of scale inhibitor and corrosion inhibitor.		
Corrective Action:		Date:	
Submersible Pump	# 1		
Comment:			
Corrective Action:		Date:	
Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 230624 Type: WELL API Number: 103-08292 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402327794	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5081720">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5081720</a>
700400252	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5081708">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5081708</a>