

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2020

Submitted Date:

03/02/2020

Document Number:

689704292**FIELD INSPECTION FORM**Loc ID 335419 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262303	WELL	PR	01/08/2002	GW	045-08011	CHEVRON GM44-20	WK

General Comment:

This is a summary of inspection report.
 On Friday 02/28/2020 at approximately 1145 hours, I, Inspector Mike Longworth, conducted a field inspection at Terra Rocky Mountain LLC GM44-20, at Location # 335419 in Garfield County, Colorado
 Follow up to inspection # 689704200
 Roust abouts changing on plumbing from braden head. Cellar has been excavated to allow repairs.

Inspected FacilitiesFacility ID: 262303 Type: WELL API Number: 045-08011 Status: PR Insp. Status: WK**Workover**Comment: Work been done on leaking well head seal.Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704293	Inspection 689704292 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5082970