

# Inspection Photos

Operator: Logos Operating  
Location/API #: 067-09136  
Date: 2-27-2020



Photo 1. View of the project area from the northeastern corner facing center.





Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with grasses such as sand dropseed, western wheatgrass, and blue grama.





Photo 3. View of the northern project area from the northeastern portion facing westward.





Photo 4. View of area along pipeline corridor where vegetation is sparse and appears to be killed. Shrubs are killed.





Photo 5. Another view of area along pipeline corridor, adjacent to access road, with little vegetative cover and sagebrush shrubs in background are killed.





Photo 6. View of reference area vegetation comprised of sagebrush shrubland with mixed grasses such as blue grama and forbs such as snakeweed, in the understory.