

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/02/2020

Submitted Date:

03/02/2020

Document Number:

699800677

**FIELD INSPECTION FORM**
 Loc ID 312419 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name    | Phone | Email                                 | Comment |
|-----------------|-------|---------------------------------------|---------|
| , Laramie       |       | cogccnotifications@laramie-energy.com |         |
| Kellerby, Shaun |       | shaun.kellerby@state.co.us            |         |

**General Comment:****COGCC Inspection Report Summary**

On Monday 3/2/20 at approximately 14:30 hours, I, Inspector Corey De Paolo, conducted an on-site inspection at LARAMIE ENERGY LLC Hancock Gulch /1 Pad, Location #312419 in Mesa County Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Multiple places with unused equipment in tank containment. See photo #0676 and #0677 with a corrective action date of 4/2/20.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

### Location

|                    |        |       |  |
|--------------------|--------|-------|--|
| <b>Lease Road:</b> |        |       |  |
| Type               | Access |       |  |
| comment:           |        |       |  |
| Corrective Action  | L      | Date: |  |

Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | CONTAINERS           |       |  |
| Comment:             | Chemical tank        |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | UNUSED EQUIPMENT  |       |            |
| Comment:           | Multiple places with unused equipment in tank containment. See photo #0676 and #0677  |       |            |
| Corrective Action: | Production facilities, shall be kept free of equipment and supplies not necessary for use on that lease. Remove unused equipment from location. | Date: | 04/02/2020 |

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |                 |       |  |
|--------------------|-----------------|-------|--|
| Type               | WELLHEAD        |       |  |
| Comment:           | Pipe rail fence |       |  |
| Corrective Action: |                 | Date: |  |
| Type               | TANK BATTERY    |       |  |
| Comment:           | Hog panels      |       |  |
| Corrective Action: |                 | Date: |  |

|                           |                                   |  |                 |
|---------------------------|-----------------------------------|--|-----------------|
| <b>Equipment:</b>         |                                   |  | corrective date |
| Type: Plunger Lift        | # 1                               |  |                 |
| Comment:                  |                                   |  |                 |
| Corrective Action:        |                                   |  | Date:           |
| Type: Ancillary equipment | # 1                               |  |                 |
| Comment:                  | Chemical tank in tank containment |  |                 |
| Corrective Action:        |                                   |  | Date:           |
| Type: Gas Meter Run       | # 1                               |  |                 |
| Comment:                  |                                   |  |                 |
| Corrective Action:        |                                   |  | Date:           |

**Tanks and Berms:**

|                    |   |          |           |         |        |       |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |       |
| PRODUCED WATER     | 2 | 300 BBLs | STEEL AST |         | ,      |       |
| Comment:           |   |          |           |         |        |       |
| Corrective Action: |   |          |           |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          |                     | Date:               |             |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |



**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Gravel                  |                       |               |                          |         |
| Compaction       |                 |                         |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |
| Ditches          |                 |                         |                       |               |                          |         |
|                  |                 | Ditches                 |                       |               |                          |         |
|                  |                 | Compaction              |                       |               |                          |         |
|                  |                 | Culverts                |                       |               |                          |         |
| Gravel           |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 699800678    | Photos for Insp. #699800677 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5083051">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5083051</a> |