

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/02/2020

Submitted Date:

03/02/2020

Document Number:

696301492**FIELD INSPECTION FORM**Loc ID 421208 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**18 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	<b>ALL INSPECTIONS</b>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421203	WELL	PR	01/01/2019	GW	123-32841	Antelope S-31	PR
421303	WELL	SI	06/01/2019	GW	123-32876	Antelope 24-31	SI
421308	WELL	PR	01/01/2015	GW	123-32878	Antelope 13-31	PR
421309	WELL	PR	10/01/2019	GW	123-32879	Antelope 23-31	PR
421313	WELL	SI	05/01/2019	GW	123-32882	Antelope 34-31	TA
421320	WELL	TA	04/25/2019	GW	123-32885	Antelope 33-31	TA
421331	WELL	TA	10/07/2019	GW	123-32889	Antelope 43-31	TA
421332	WELL	TA	10/07/2019	GW	123-32890	Antelope 44-31	TA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	34-31 Missing Wellhead Sign		
Corrective Action:	Comply with Rule 210.b	Date:	03/30/2020

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused Hydraulic Pumping Unit, Wellhead parts, wood posts. See photos		
Corrective Action:	Comply with Rule 603.f.	Date:	03/30/2020

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed Wire		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Bradenhead	# 7		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	

Type: Pump Jack	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLS	STEEL AST		40.352970,-104.361680
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--	--	--	--

**Inspected Facilities**Facility ID: 421203 Type: WELL API Number: 123-32841 Status: PR Insp. Status: PR**Producing Well**Comment: PRCorrective Action: Date: Facility ID: 421303 Type: WELL API Number: 123-32876 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: Comment: SICorrective Action: Date: Facility ID: 421308 Type: WELL API Number: 123-32878 Status: PR Insp. Status: PR**Producing Well**Comment: PRCorrective Action: Date: Facility ID: 421309 Type: WELL API Number: 123-32879 Status: PR Insp. Status: PR**Producing Well**Comment: PRCorrective Action: Date: Facility ID: 421313 Type: WELL API Number: 123-32882 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: Comment: TACorrective Action: Date: Facility ID: 421320 Type: WELL API Number: 123-32885 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: Comment: TACorrective Action: Date: Facility ID: 421331 Type: WELL API Number: 123-32889 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: Comment: TACorrective Action: Date:

Facility ID: 421332 Type: WELL API Number: 123-32890 Status: TA Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. 34-31 - Unused equipment and trash, also Missing Wellhead sign. See photos. Corrective Action Date 03.30.2020</a>	petrie	03/02/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696301493	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5083143">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5083143</a>