

Inspection Photos
Location Name: UPRR 23 PAN AM M #2
Location ID: 319982



Photo #1 tanks




Photo #2 missing Bullplug

Inspection Photos Location Name: UPRR 23 PAN AM M #2 Location ID: 319982



Mar 3, 2020 at 10:32:55 AM
 N 39° 56' 38", W 104° 35' 3"
 307° NV
 Adams County Inspection

Photo #3 separator



Station #	Ad	Gr	Station Name	Sec	TwNShip	Range
012872			UPRR 23 PAN AM M #2	19	15	14W
Radio #	Producer Name			Mtr Tube Size		
880-0873	K P Kaufman			3068		
Transmitter / Module #	Federal #			County		
80001715 / ME145015	State #			Adams		
State / Span	Up / Dwn	Diff / Span	Temp / Span	Absolute	Mtr #	
0-360	Up	0-250	0-150	8.2	T000736	
Test Date	OP Size	Beta	Sample Date	H2S	Sample Date	H2S
4-13-11	1.500	1.0	Replaced Berton with a Total Flow			
4-14-12	1.500		11-19-12	3.0		
4-2-13	1.500	0.49	11-15-13	3.5		
4-19-14	1.500	.49	11-19-14	2.1		
11-2-15	1.500	.49	11-19-15	3.0		
5-25-17	1.500		5-25-17	3.0		
5-16-18	1.500	.49	5-16-18	2.4		
12-2-18	1.500	.49	12-2-18	2.0		

Mar 3, 2020 at 10:34:29 AM
 N 39° 56' 38" W 104° 35' 3"
 46° NV
 Adams County Inspection

Photo #4 meter out of calibration

Inspection Photos
Location Name: UPRR 23 PAN AM M #2
Location ID: 319982



Photo #5 wellhead