

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/04/2020

Submitted Date:

03/04/2020

Document Number:

688307068**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
320678 _____ Sherman, Susan _____ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10646Name of Operator: AXIS EXPLORATION LLCAddress: 370 17TH ST SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Antonioli, Philip	720-345-4603	PAntonioli@extractionog.com	
Extraction OG	720-370-5540	COGCCInspections@extracti onog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204438	WELL	SI	06/01/2018	GW	005-06523	Cavanaugh 3	SI

General Comment:[MIT Inspection, failed](#)

Inspected FacilitiesFacility ID: 204438 Type: WELL API Number: 005-06523 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: MIT
Three bbls to load hole,
Pressured up to 698 psi and within 5 mins fell to 10 psi. Operator charted test for 15 min.Corrective Action: Repair then retest or plug and abandon per approved Form 6 NOI.Date: 04/15/2020**BradenHead**Comment: Dead

Corrective Action: _____

Date: _____

WorkoverComment: Ensign 351

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688307108	Axis Exploration Cavanaugh 3 rig sign at Manila	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5085607
688307109	Axis Exploration Cavanaugh 3 rig signs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5085608
688307110	Axis Exploration Cavanaugh 3 rig	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5085609
688307111	Axis Exploration Cavanaugh 3 wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5085610
688307112	Axis Exploration Cavanaugh 3 Anytime Testing truck	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5085611