



**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:		Date:	_____

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

	Type WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

**Equipment:**

					corrective date
Type: Bradenhead	# 1				
Comment:	Appears to be plumbed to surface.				
Corrective Action:			Date:		
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:			Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 250252 Type: WELL API Number: 123-18055 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On Wednesday 3/4/20 at approximately 1115 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at UPV 23-10I4 of Noble Energy at API # 05-123-18055in Weld County, Colorado.                      While there, I observed a production well that is SI.                      No violation of the COGCC rules were observed at the time of inspection.                      This is a summary of inspection report.                      Continuing education inspections</p>	burnsa	03/04/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699101202	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5085682">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5085682</a>