

## Inspection Photos

Location Name: Starkey 14-28-969

Facility ID: CE&P 454686

Inspection Date: February 27, 2020



**Aerial view of the location. The blue oval is around the tank battery and the red oval is around pit ID 414554 (GISOnline Maps).**



**Starkey Production Pit sign. Note oil accumulation on upper pit liner and soil at the southeast corner of the pit.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Starkey 14-28-969

Facility ID: CE&P 454686

Inspection Date: February 27, 2020



Gaps in the base of the wildlife mesh on the east side of the pit. Note that pipe support cribbing is in disrepair.



Gaps in the base of the wildlife mesh on the east side of the pit.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Starkey 14-28-969

Facility ID: CE&P 454686

Inspection Date: February 27, 2020



**Wildlife foot prints located on the perimeter of the pit.**



**Free product present on ~20% of the pit fluid and liner.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Starkey 14-28-969

Facility ID: CE&P 454686

Inspection Date: February 27, 2020



Free product present on of the pit fluid (~20%) and liner.



Sediment encroaching on pit liner.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Starkey 14-28-969

Facility ID: CE&P 454686

Inspection Date: February 27, 2020



**Subsidence around rig anchor supports on the west side of the pit.**



**Subsidence around rig anchor supports on the west side of the pit and the netting support bollards leaning towards the east.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Starkey 14-28-969

Facility ID: CE&P 454686

Inspection Date: February 27, 2020



**Oil stained soil on the southeast corner of the pit.**



**Sitewide vegetation.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Starkey 14-28-969

Facility ID: CE&P 454686

Inspection Date: February 27, 2020



**Flow line support in disrepair.**



**Flow line cribbing and support in disrepair.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Starkey 14-28-969**  
**Facility ID: CE&P 454686**  
**Inspection Date: February 27, 2020**



**Tank battery sign, impacted material and vegetation.**



**Impacted material around the load out area of the tank battery.**





## Inspection Photos

Location Name: Starkey 14-28-969

Facility ID: CE&P 454686

Inspection Date: February 27, 2020



**Potential impacted fluids within the tank battery secondary containment.**



**Photo #18 – Trough containing potential impacted fluid located beneath the tank battery load out.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Starkey 14-28-969

Facility ID: CE&P 454686

Inspection Date: February 27, 2020



**Movement of 12-16-inch poly pipe located east of Pit ID 414554.**



**Uncapped manifold on the eastern side of the pit.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Starkey 14-28-969

Facility ID: CE&P 454686

Inspection Date: February 27, 2020



**Hoses and poly line resting directly on the pit liner.**



**Trash on location**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Starkey 14-28-969

Facility ID: CE&P 454686

Inspection Date: February 27, 2020



**Uncontrolled access to the location.**



**Net support guy wire wearing through pipe insulation and pipe.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Starkey 14-28-969

Facility ID: CE&P 454686

Inspection Date: February 27, 2020



**Gaps in net secured with rocks.**



**Trash and debris on pit liner within the pit.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Starkey 14-28-969

Facility ID: CE&P 454686

Inspection Date: February 27, 2020



**Site wide trash.**



**Unused equipment within the tank battery secondary containment.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Starkey 14-28-969

Facility ID: CE&P 454686

Inspection Date: February 27, 2020



**Potential impacted fluids within the tank battery secondary containment.**



**Trash and debris within the tank battery secondary containment.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Starkey 14-28-969

Facility ID: CE&P 454686

Inspection Date: February 27, 2020



**Load out hose draped over equipment, staining on the exterior of the tank battery secondary containment.**



**Trash within the tank battery secondary containment.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources