

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume		corrective date
Type: Ancillary equipment	# 1			
Comment:	TELEMETRY EQUIPMENT			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	IS PLUMBED TO SURFACE			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 264918 Type: WELL API Number: 071-07743 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						
Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID: <u>268627</u>	Lat: <u>37.180512</u>	Long: <u>-104.810433</u>		
Reference Point: <u>SE</u>	Other: _____	Length: <u>70</u>	Width: <u>30</u>			
Lining:						
Liner Type: _____			Liner Condition: _____			
Comment: <input style="width: 95%;" type="text"/>						Date: _____
Corrective Action: <input style="width: 95%;" type="text"/>						
Fencing:						
Fencing Type: _____			Fencing Condition: _____			
Comment: <input style="width: 95%;" type="text"/>						Date: _____
Corrective Action: <input style="width: 95%;" type="text"/>						
Netting:						
Netting Type: _____			Netting Condition: _____			
Comment: <input style="width: 95%;" type="text"/>						Date: _____
Corrective Action: <input style="width: 95%;" type="text"/>						
Anchor Trench Present: <u>NO</u>	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>NO</u>				
Comment: PHOTO 4: FLUID LEVEL IS ABOVE 2' FREEBOARD MARKER, I SPOKE WITH ED ROMERO WITH EVERGREEN TO HAVE PIT PULLED.						Date: <u>02/28/2020</u>
Corrective Action: Lower fluid level so at least two feet of freeboard exists per Rule 902.b.						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402326715	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5080476
695102224	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5080460