

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
	Comment: Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:
 Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
	Comment: AG Fence		
Corrective Action:		Date:	

Equipment:

					corrective date
Type: Bradenhead	# 1				
Comment:	Appears to be plumbed to surface				
Corrective Action:		Date:			
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:		Date:			
Type: Ancillary equipment	# 1				
Comment:	Automation				
Corrective Action:		Date:			

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 206919 Type: WELL API Number: 013-06414 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 3/4/2020 at approximately 1520 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at an Extraction Oil & Gas Inc.: Anderson MB 33-5 at API #05-013-06414 in Boulder County Colorado. While there, I observed producing well site. This is a follow up inspection per Doc. # 699300655 During this inspection the following possible compliance issue has been addressed: 603.f Debris: Dead weeds around wellhead, see photo 2. Location is muddy & the weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	03/04/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301202	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5085986