

Inspection Photos
Operator: Williford Resources
API#: 067-06607
Date: 3/4/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Vegetation is largely comprised of sagebrush, snakeweed, and weeds such as cheatgrass.



Photo 3. View of reference area vegetation west of the project area, similar to vegetation in the western project area.