

Inspection Photos
Operator: Williford Resources
API#: 067-06671
Date: 3/4/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of hydrocarbon-stained material remains in the northwestern project area.



Photo 3. View of soil pile with what appears to be impacted material, stored within the northwestern project area.



Photo 4. View of spotted knapweed plant observed along the eastern edge of the project area. Approximately 20 individuals observed in a dormant condition.



Photo 5. View of reference area vegetation west of the project area, largely comprised of sagebrush, sand dropseed, snakeweed, and cheatgrass.