

# Inspection Photos

API: 061-06876

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 3/6/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06876 | Date: 3/6/2020

## Inspection Photos



**Photo 1.** Facing east at the beginning of the access road. The road is bare of vegetation and not reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06876 | Date: 3/6/2020

## Inspection Photos



**Photo 2.** The cattle guard has been removed and left near the beginning of the access road. The cattle guard and cement need to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06876 | Date: 3/6/2020

## Inspection Photos



**Photo 3.** Facing south along the former access road. The access road is bare of vegetation and there is signs of wind erosion occurring.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06876 | Date: 3/6/2020

## Inspection Photos



**Photo 4.** The disturbance of the access road was measured to be approximately 50 feet wide.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06876 | Date: 3/6/2020

## Inspection Photos



**Photo 5.** Facing east toward the location. The location does not have desirable vegetation establishment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06876 | Date: 3/6/2020

## Inspection Photos



**Photo 6.** Facing north at the center of the location. The location does not have desirable vegetation establishment. There is bare ground and weeds throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06876 | Date: 3/6/2020

## Inspection Photos



**Photo 7.** North side of the location facing south toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06876 | Date: 3/6/2020

## Inspection Photos



**Photo 8.** View groundcover at the location shows bare soil which is susceptible to erosion. There is also weed debris (Kochis sp.) shown in the photo.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06876 | Date: 3/6/2020

## Inspection Photos



**Photo 9.** Facing north toward the surrounding reference area which consists of desirable vegetation such as Blue grama, Sand dropseed, among other native species.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06876 | Date: 3/6/2020