

Inspection Photos  
Operator: Williford Resources  
API#: 067-06772  
Date: 3/4/2020



Photo 1. View of the project area from the southwestern corner facing center.





Photo 2. View of the western project area from the southwestern corner facing northward. Vegetation is in a dormant condition with scattered shrubs such as rubber rabbitbrush and sagebrush, as well as weedy annual grasses and forbs, similar to the reference area.





Photo 3. View of reference area vegetation west of the project area, largely comprised of scattered shrubs such as rubber rabbitbrush and sagebrush, as well as weedy annual grasses and forbs,