

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2020

Submitted Date:

03/06/2020

Document Number:

700700228**FIELD INSPECTION FORM**

Loc ID 334891	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				Findings: 12 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259573	WELL	PR	03/20/2001	GW	045-07751	BERNKLAU RWF 314-33	PR
259574	WELL	PR	03/20/2001	GW	045-07752	BERNKLAU RWF 323-33	PR
259575	WELL	PR	03/20/2001	GW	045-07753	BERNKLAU RWF 324-33	PR
289637	WELL	PR	11/28/2007	GW	045-13829	HILLTOP 2F2 RANCH LLC RWF 413-33	PR
289638	WELL	PR	11/28/2007	GW	045-13828	HILLTOP 2F2 RANCH LLC RWF 14-33	PR
289639	WELL	PR	11/28/2007	GW	045-13827	HILLTOP 2F2 RANCH LLC RW 414-33	PR
289640	WELL	PR	03/07/2007	GW	045-13826	HILLTOP 2F2 RANCH LLC RWF411-4	PR
289641	WELL	PR	11/28/2007	GW	045-13825	HILLTOP 2F2 RANCH LLC RWF 511-4	PR

General Comment:

COGCC Inspection Report Summary

On Friday 3/6/20 at approximately 9:30 AM, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RWF323-33, at Location # 334891 in Garfield Colorado.

While there, I observed normal production operations.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Type	SEPARATOR				
Comment:					
Corrective Action:				Date:	

Equipment:					corrective date
Type: Ancillary equipment	# 1				
Comment:	chemical tank				
Corrective Action:				Date:	
Type: Plunger Lift	# 8				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 11				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 7				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:	shared containment with condensate tanks					
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	259573	Type:	WELL	API Number: 045-07751	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	
Facility ID:	259574	Type:	WELL	API Number: 045-07752	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	
Facility ID:	259575	Type:	WELL	API Number: 045-07753	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	
Facility ID:	289637	Type:	WELL	API Number: 045-13829	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	
Facility ID:	289638	Type:	WELL	API Number: 045-13828	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	
Facility ID:	289639	Type:	WELL	API Number: 045-13827	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	
Facility ID:	289640	Type:	WELL	API Number: 045-13826	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	
Facility ID:	289641	Type:	WELL	API Number: 045-13825	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing					
Corrective Action:					Date:	

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Culverts				

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700233	Photos for RWF 323-33	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5088444