

Inspection Photos
Operator: Williford Resources
API#: 067-06557
Date: 3/4/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of tubing stored within the central project area, needs to be removed.



Photo 3. View of debris scattered around the outer edges of the project area.



Photo 4. View of unused tank that needs to be removed and Russian knapweed that needs treatment northeast of the project area.



Photo 5. View of reference area vegetation west of the project area, largely comprised of sagebrush shrubland, in a dormant vegetative condition.