

Inspection Photos
Location Name: Ballantine 34-9 #32-2
API: 05-067-08075



**Carsonite marker near rig anchor by entrance to location.
Corrective action from previous inspection.**



Ballantine 34-9 #32-2 production equipment.

Inspection Photos
Location Name: Ballantine 34-9 #32-2
API: 05-067-08075



Ballantine 34-9 #32-2 well head. Photo taken from near PA Red Willow well.



Discolored soil begins adjacent to Hilcorp well.

Inspection Photos
Location Name: Ballantine 34-9 #32-2
API: 05-067-08075



Ballantine 34-9 #32-2 well head. Excavation for PA well in the background. Hilcorp well is uphill from Red Willow well head location.



Drainage pattern with discolored soil extending SE from well head.