

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/05/2020

Submitted Date:

03/06/2020

Document Number:

689901865**FIELD INSPECTION FORM**Loc ID 324831 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 83130Name of Operator: STRACHAN EXPLORATION INCAddress: 383 INVERNESS PKWY, STE 360City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Strachan, Steve	(303) 785-7006	sms@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213004	WELL	PR	02/14/2007	OW	061-06365	FRAZEE 2-6	RI

General Comment:

This is a location and stormwater inspection.

This is also a follow up of the previous inspection document number 689900683.

See attached photos and additional details within this report

Location**Lease Road:**

Type	Access		
comment:	The access road has been regraded and graveled. No issues were observed.		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign is posted at wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	The various equipment and debris observed in previous inspection has been removed. The cement pad was noted in the previous inspection however, the cement pad has not been removed. The cement pad is considered unused equipment and needs to be removed. Previous corrective action remains.		
Corrective Action:	Comply with Rule 603.f .	Date:	08/15/2019

Overall Good: ☐**Spills:**

Type	Area	Volume	
Other			
Comment:	There were no oil stained soils observed at the surface near the well head, pumpjack, or shed. Spills observed during previous inspection appear to have been cleaned up.		
Corrective Action:		Date:	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type		
Comment:	The fence around the equipment has been repaired however, the fences are only 2 strand barb wire and may not prevent livestock entry.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition	
-----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				Adequate
Comment:	The berms around the tanks appear to have been repaired and maintained.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: The cattle guard along the access road has been repaired and maintained. The access road has been regraded, graveled, and is maintained. No stormwater issues were observed. It does not appear vehicles are traveling outside of the access road. Material handling and spill prevention appears to have been implemented. Barrels and buckets with lubricants have been removed.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689901866	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5089003