

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402338589

Date Received:

03/10/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 8 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Romana Cowden

720-951-5895

rcowden@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 698100127

Inspection Date: 02/25/2020

FIR Submit Date: 02/26/2020

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334069

Location Name: SHIDELER-68S93W Number: 1SWNE County: _____

Qtrqr: SWNE Sec: 1 Twp: 8S Range: 93W Meridian: 6

Latitude: 39.398990 Longitude: -107.719270

FACILITY - API Number: 05-045- -00 Facility ID: 334069

Facility Name: SHIDELER-68S93W Number: 1SWNE

Qtrqr: SWNE Sec: 1 Twp: 8S Range: 93W Meridian: 6

Latitude: 39.398990 Longitude: -107.719270

CORRECTIVE ACTIONS:

1 CA# 136731

Corrective Action: Immediately repair or install secondary containment devices per Rule 605.a.(4). Provide 48-hour advance notice to COGCC EPS prior to secondary containment inspection and repair. Submit documentation of tank battery liner repairs conducted in response to previous inspection report via FIRR within 30 days.

Date: 10/28/2019

Response: CA COMPLETED

Date of Completion: 03/04/2020

Operator Comment: Liner was repaired. Delay due to frozen snow in containment.

COGCC Decision: _____

COGCC
Representative:

2 CA# 136732

Corrective Action: Immediately repair or install secondary containment devices per Rule 605.a.(4). Provide 48-hour advance notice to COGCC EPS prior to secondary containment inspection and repair. Submit documentation of tank battery liner repairs conducted in response to previous inspection report via FIRR within 30 days.

Date: 10/28/2019

Response: CA COMPLETED

Date of Completion: 03/04/2020

Operator
Comment:

Liner was repaired. Delay due to frozen snow in containment.

COGCC Decision: _____

COGCC
Representative:

3 CA# 136733

Corrective Action: Install bullplug or secondary containment device to prevent releases of fluid, per Rule 906.d.

Date: 03/12/2020

Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Response: CA COMPLETED

Date of Completion: 03/04/2020

Operator
Comment:

Valve was replaced.

COGCC Decision: _____

COGCC
Representative:

7 CA# 136737

Corrective Action: Remove and properly dispose of E&P waste per Rule 907.e. Comply with Rule 603.f.

Date: 03/27/2020

Response: CA COMPLETED

Date of Completion: 03/04/2020

Operator
Comment:

Drums were removed.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 3/10/2020 3:06:15 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files