

Inspection Photos
Location Name: RWF 21-18
Location ID: 335569
Inspection Date: March 6, 2020



Aerial view of the location.



Location sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: RWF 21-18
Location ID: 335569
Inspection Date: March 6, 2020



Produced Water steel AST missing capacity label.



Trash and debris located around the separators.



Inspection Photos
Location Name: RWF 21-18
Location ID: 335569
Inspection Date: March 6, 2020



Trash and debris located around the separators.



Trash and debris located around the wellheads.



Inspection Photos
Location Name: RWF 21-18
Location ID: 335569
Inspection Date: March 6, 2020



Unused equipment located on the southwest corner of the well pad.



1-inch riser adjacent to RWF 312-18 wellhead.



Inspection Photos
Location Name: RWF 21-18
Location ID: 335569
Inspection Date: March 6, 2020



Localized accumulation of oily waste around wellhead.



Localized accumulation of oily waste around wellhead.



Inspection Photos
Location Name: RWF 21-18
Location ID: 335569
Inspection Date: March 6, 2020



Wildlife fencing around wellheads in disrepair, vehicle tracking on location and fluids pooling around wellheads.



Localized accumulations of precipitation inside secondary containment area.



Inspection Photos
Location Name: RWF 21-18
Location ID: 335569
Inspection Date: March 6, 2020



Vehicle tracking on location.



Vehicle tracking on location.

