

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/10/2020

Submitted Date:

03/10/2020

Document Number:

688307233

FIELD INSPECTION FORM
 Loc ID 317368 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 20275

Name of Operator: CORAL PRODUCTION CORP

Address: 1600 STOUT ST STE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Wieger, Jim	(303) 623-3573	JIMWIEGER@QWESTOFFICE.NET	
Young, Rob		rob.young@state.co.us	
Chonka, Jim	(303) 623-3573	jpchonka@netscape.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269686	WELL	PR	04/01/2012	OW	121-10711	CHRISTIANSEN B-5	SI

General Comment:Spill Reinspection

On 3/5/2020 produced water was running from an animal hole in the pit berms on the south end of the pit, into grassy areas east and west, under a barbed wire fence, down a gully and into a pond in the pasture. Produced water was still running out the animal hole on 3/10/2020 and there was no evidence of remedial work being done to stop it. COGCC EPS and operator were contacted by inspector and a contractor was to be in location today, 3/10/2020 to fix animal holes in the berms and stop the water from leaking from the produced water pit. Operator said that the produced water going into the west pond was for livestock. A Form 19I was submitted. See attached photos.

Inspected FacilitiesFacility ID: 269686 Type: WELL API Number: 121-10711 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: The Christiansen B-5 and B3 wells were shut in for the spill. No water was coming out of the outfall pipe from the produced water tanks at the tank battery on 3/10/2020. The injection well was already shut in.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					
Berms	Fail					

Comment: Maintain animal holes in pit berms and maintain erosion area in gully between the produced water pit and the pond. Sediment was transported of location and formed a deltalike area in the pond. See attached photos.

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 04/08/2020

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: Other: Length: Width:

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: Fiberglass tank on south side of pit has pipe from pit going into it. Tank was empty at time of inspection, including no sediment. The Form 7s indicate that 9550 bbls of water was produced from each of the two wells in 29 days of the month. The spill continued from 3/5/2020 to 3/10/2020 as observed by the inspector.

Corrective Action: Contact COGCC EPS for supplemental Form 19s.

Date: 03/25/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688307242	Coral Production Christiansen B-5	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5091809