

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/09/2020

Submitted Date:

03/11/2020

Document Number:

690101763

**FIELD INSPECTION FORM**
 Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 \_\_\_\_\_ Maclaren, Joe \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_
**Operator Information:**

OGCC Operator Number: 39560

Name of Operator: TOP OPERATING COMPANY

Address: 3609 S WADSWORTH BLVD STE 340

City: LAKEWOOD State: CO Zip: 80235

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
HERRING, PAUL		paul.herring@topoperating.com	
HERRING, MURRAY J		murray.herring@topoperating.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241832	WELL	SI		OW	123-09622	DITIRRO, JOHN 1-A	EG
472962	SPILL OR RELEASE	AC	03/06/2020		-	Beneath former location of pumpjack	EG

**General Comment:**

Engineering Integrity inspection performed on March 9th, 2020 in response to initial form 19 spill report Doc #402332979 received by COGCC on 03/05/2020 that outlines: The historic release (unknown quantity) was discovered beneath the former pumpjack location. Stained soil was observed to approximately 3-4 feet below ground surface.

Details of Corrective Actions required identified during this field inspection are located in the flowline section of this report.  
Photos uploaded.

**Inspected Facilities**

Facility ID: 241832 Type: WELL API Number: 123-09622 Status: SI Insp. Status: EG

**Flowline**

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: 3" Material: Carbon Steel  
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Off location flowline abandonment work observed in progress; flowline has been flushed, risers removed at wellhead/ facility and ends sealed (welded caps) below grade.

Corrective Action: COGCC form 42 Pre-abandonment notice has not been filed with COGCC. (Director approval required for off location flowline abandonment/ not completed)

Comply with COGCC rule 1105.d. Pre-abandonment notice requirements for flowline or crude oil transfer line for inspection.

Provide notice to the surface owner and the relevant local government simultaneously with submitting notice to the Director pursuant to this Rule 1105.d.

Date: 03/14/2020

Facility ID: 472962 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

**COGCC Comments**

Comment	User	Date
Well (Ditirro, John 1-A) has been plugged and abandoned; COGCC form 42 notice of start of well plugging operations Doc #402305104 received on 02/06/2020. Top contractors (Amen Oilfield Services) were on location at the time of this field inspection. Excavation and remediation work pertaining to impacted soils around the (PA) wellhead is in progress.	maclarej	03/11/2020
As outlined in the CA section of COGCC supplemental form 19 Doc #402332979: Historical soil impacts were discovered during removal of the pumpjack. All facility equipment is being removed and the well has been P&A. Historical release.		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101767	Signage at facility; view S towards PA wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5092293">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5092293</a>
690101768	Excavation at PA well; off location flowline (view S)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5092294">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5092294</a>
690101769	Flowline abandonment; welded cap on cut end	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5092295">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5092295</a>