

Inspection Photos
Operator: BP America
API#: 067-05157
Date: 3/10/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of erosional channeling and failed berm within the southeastern project area.



Photo 3. View of area where stormwater flows around facilities creating erosive channel.



Photo 4. View of another erosional channel flowing southeast, off of the project area into adjacent crop field (reference area) not vegetated at this time.