

Inspection Photos
Operator: BP America
API#: 067-05115
Date: 3/10/2020



Photo 1. View of the southern project area from the southeastern entrance facing center.



Photo 2. View of the northern project area from the western edge facing center.



Photo 3. View of erosional rilling near flowing down the access road in the southeastern project area. Russian thistle debris needs to be removed.



Photo 4. View of more erosional channeling running off the north end of the southern working area. Cobble placed within the project area is not functioning to stabilize erosion here.



Photo 5. View of the fill slope dividing the northern and southern working areas. Revegetation is progressing largely with rubber rabbitbrush, intermediate wheatgrass, and western wheatgrass, although weedy in portions with cheatgrass and Russian thistle.



Photo 6. View of reference area vegetation comprised of sagebrush shrubland with grassy understory, dominated by thickspike wheatgrass, and James galleta.