

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/11/2020

Submitted Date:

03/11/2020

Document Number:

700700261

**FIELD INSPECTION FORM**

Loc ID 335551 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10447

Name of Operator: URSA OPERATING COMPANY LLC

Address: 950 17TH STREET, SUITE 1900

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293336	WELL	PR	10/01/2017	GW	045-14947	DEVER C9	PR
293337	WELL	PR	11/06/2007	GW	045-14946	DEVER C8	PR
293338	WELL	PR	12/01/2019	GW	045-14945	Dever C7	PR
293341	WELL	PR	11/01/2019	GW	045-14942	DEVER C4	PR
293342	WELL	PR	11/01/2019	GW	045-14941	DEVER C3	PR

**General Comment:****COGCC Inspection Report Summary**

On Wednesday 3/11/20 at approximately 1:00 PM, I, Inspector Scott Ramsey, conducted a routine inspection at URSA Dever E pad, at Location # 335551 in Garfield Colorado.

During this inspection the following possible compliance issues were observed:

- Open hole with potential for wildlife to be trapped.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

## Location

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	open hole in front of separator		
Corrective Action:	prevent wildlife from entering open hole	Date:	04/15/2020

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Emission Control Device	# 1		corrective date
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	chemical tank		
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	one (1) tank is heated				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		,
Comment:	shared containment with condensate tanks				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:				
Corrective Action:			Date:	
<b><u>Venting:</u></b>				
Yes/No	NO			
Comment:				
Corrective Action:			Date:	
<b><u>Flaring:</u></b>				
Type	Ignitor/Combustor			
Comment:				
Corrective Action:			Date:	

Inspected Facilities				
Facility ID:	293336	Type:	WELL	API Number: 045-14947 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	293337	Type:	WELL	API Number: 045-14946 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	293338	Type:	WELL	API Number: 045-14945 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	293341	Type:	WELL	API Number: 045-14942 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	293342	Type:	WELL	API Number: 045-14941 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	producing			
Corrective Action:				Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Culverts				
Ditches		Ditches				
Berms		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Safety personal showed up with snow fence to put up around open hole.	ramseys	03/11/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700272	261	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5094808">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5094808</a>