

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/12/2020

Submitted Date:

03/12/2020

Document Number:

696301576

**FIELD INSPECTION FORM**Loc ID 415293 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10575

Name of Operator: 8 NORTH LLC

Address: 370 17TH STREET SUITE 5300

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                                 | Comment        |
|--------------|-------|---------------------------------------|----------------|
| ,            |       | COGCCInspections@extracti<br>onog.com | All Inspectors |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 415292      | WELL | PR     | 10/10/2017  | OG         | 123-31036 | WILSON 1160-29-22 | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |   |       |            |
|----------------------|---|-------|------------|
| <b>Signs/Marker:</b> |   |       |            |
| Type                 | TANK LABELS/PLACARDS  |       |            |
| Comment:             | Produced Water Tank - Missing Capacity and NFPA is fading, see photos |       |            |
| Corrective Action:   | Comply with Rule 210.d.   | Date: | 03/27/2020 |
| Type                 | WELLHEAD  |       |            |
| Comment:             | Adequate  |       |            |
| Corrective Action:   |   | Date: |            |
| Type                 | BATTERY   |       |            |
| Comment:             | Adequate  |       |            |
| Corrective Action:   |   | Date: |            |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | OTHER  |       |            |
| Comment:           | Stained Soil at Wellhead, see photos   |       |            |
| Corrective Action: | For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e." | Date: | 03/27/2020 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |             |       |  |
|--------------------|-------------|-------|--|
| <b>Fencing/:</b>   |             |       |  |
| Type               | WELLHEAD    |       |  |
| Comment:           | Panels      |       |  |
| Corrective Action: |             | Date: |  |
| Type               | LOCATION    |       |  |
| Comment:           | Barbed Wire |       |  |
| Corrective Action: |             | Date: |  |

|                                   |                                  |       |                 |
|-----------------------------------|----------------------------------|-------|-----------------|
| <b>Equipment:</b>                 |                                  |       | corrective date |
| Type: Bradenhead                  | # 1                              |       |                 |
| Comment:                          | Appears to be plumbed to Surface |       |                 |
| Corrective Action:                |                                  | Date: |                 |
| Type: Horizontal Heated Separator | # 1                              |       |                 |
| Comment:                          |                                  |       |                 |
| Corrective Action:                |                                  | Date: |                 |

|                                 |     |  |       |
|---------------------------------|-----|--|-------|
| Type: Gas Meter Run             | # 1 |  |       |
| Comment:                        |     |  |       |
| Corrective Action:              |     |  | Date: |
| Type: Vertical Heated Separator | # 1 |  |       |
| Comment:                        |     |  |       |
| Corrective Action:              |     |  | Date: |
| Type: Emission Control Device   | # 1 |  |       |
| Comment:                        |     |  |       |
| Corrective Action:              |     |  | Date: |
| Type: Pump Jack                 | # 1 |  |       |
| Comment:                        |     |  |       |
| Corrective Action:              |     |  | Date: |

**Tanks and Berms:**

|                    |   |          |             |         |        |       |
|--------------------|---|----------|-------------|---------|--------|-------|
| Contents           | # | Capacity | Type        | Tank ID | SE GPS |       |
| PRODUCED WATER     | 1 | OTHER    | BV CONCRETE |         | ,      |       |
| Comment:           |   |          |             |         |        |       |
| Corrective Action: |   |          |             |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 24 BBLS  |  |
| Other (Type)     |          |  |

**Berms**

|                    |                                      |                     |                     |             |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
| Type               | Capacity                             | Permeability (Wall) | Permeability (Base) | Maintenance |
|                    |                                      |                     |                     |             |
| Comment:           | Shares berm with the Crude Oil Tanks |                     |                     |             |
| Corrective Action: |                                      |                     |                     |             |
|                    |                                      |                     |                     | Date:       |

|                    |   |          |                |         |        |       |
|--------------------|---|----------|----------------|---------|--------|-------|
| Contents           | # | Capacity | Type           | Tank ID | SE GPS |       |
| PRODUCED WATER     | 1 | 500 BBLS | FIBERGLASS AST |         | ,      |       |
| Comment:           |   |          |                |         |        |       |
| Corrective Action: |   |          |                |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|          |                                      |                     |                     |             |
|----------|--------------------------------------|---------------------|---------------------|-------------|
| Type     | Capacity                             | Permeability (Wall) | Permeability (Base) | Maintenance |
|          |                                      |                     |                     |             |
| Comment: | Shares berm with the Crude Oil Tanks |                     |                     |             |

|                    |   |          |           |         |                       |  |
|--------------------|---|----------|-----------|---------|-----------------------|--|
| Corrective Action: |   |          |           |         | Date:                 |  |
| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |  |
| CRUDE OIL          | 2 | 500 BBLs | STEEL AST |         | 40.897000,-104.124860 |  |
| Comment:           |   |          |           |         |                       |  |
| Corrective Action: |   |          |           |         | Date:                 |  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

| Inspected Facilities |        |       |      |             |           |         |    |               |    |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 415292 | Type: | WELL | API Number: | 123-31036 | Status: | PR | Insp. Status: | PR |
| Producing Well       |        |       |      |             |           |         |    |               |    |
| Comment:             | PR     |       |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      | Date:       |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <a href="#">Routine Field Inspection. Stained Soil at Wellhead. Produced Water tank missing Capacity and NFPA label is Fading.</a> | petrie | 03/12/2020 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 696301577    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5094898">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5094898</a> |