

Inspection Photos
Operator: BP America
API#: 067-07868
Date: 3/10/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of area adjacent to the southwestern corner of the working area where erosion continues. Cobble BMP placed in channel was not sufficient to stabilize this area and is largely washed downstream.




Photo 3. View of headcut erosion adjacent to the southwestern corner of the well pad. Hard hat in place for scale



Photo 4. View of additional headcut erosion observed at well pad entrance where stormwater flows over the access road.



Photo 5. View of reference area vegetation comprised of sagebrush shrubland with grassy understory, dominated by thickspike wheatgrass, and James galleta.