

Inspection Photos

API: 071-09034

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/9/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09034 | Date: 3/9/2020

Inspection Photos



Photo 1. The culvert outlet has filled in with sediment at Lat/Long:37.05764,-104.81458.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09034 | Date: 3/9/2020

Inspection Photos



Photo 2. Facing west at the culvert inlet at Lat/Long:37.05764,-104.81458.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09034 | Date: 3/9/2020

Inspection Photos



Photo 3. There is vehicle rutting along the main access road near the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09034 | Date: 3/9/2020

Inspection Photos



Photo 4. The sides of the main road has eroded a deep channel at Lat/Long:37.041830,-104.81016.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09034 | Date: 3/9/2020

Inspection Photos



Photo 5. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09034 | Date: 3/9/2020