

Final Reclamation Inspection

March 12, 2020

Operator: PETROSHARE CORPORATION- 10454

API: 05-039-06428

Inspection Document #: 697501208

Elbert County, CO

SESE Section 19 T6S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: RMPCO-EVERETT-UPRR #1

API: 05-039-06428



Photo 1. Google Earth aerial imagery taken 9/29/1999 illustrating well and battery location during operations.

Inspection Photos

Location Name: RMP CO-EVERETT-UPRR #1

API: 05-039-06428



Photo 2. Google Earth aerial imagery taken 6/15/2010 illustrating well and battery location after the location was plugged in 2003. Both the well and battery locations do not meet Rule 1004 standards.

Inspection Photos

Location Name: RMP-CO-EVERETT-UPRR #1

API: 05-039-06428



Photo 3. Photo taken from the western battery location on 4/20/2018, facing West. Gully erosion is evident and BMP is in disrepair. Operator has failed to complete final reclamation activities.

Inspection Photos
Location Name: RMP-CO-EVERETT-UPRR #1
API: 05-039-06428



Photo 4. Photo taken from the gully erosion along the western battery location on 4/20/2018, facing West. Erosion continues west, off location.

Inspection Photos
Location Name: RMP-EO-1000-UPRR #1
API: 05-039-06428



Photo 5. Photo taken from the western battery location on 4/20/2018, facing East. Vegetation at the battery location is not reflective of reference area vegetative level and does not meet Rule 1004 standards. Operator has failed to complete final reclamation activities.




Photo 6. Photo taken from the northern battery location on 4/20/2018, facing West. See comments under Photo 3.

Inspection Photos
Location Name: RMPCO-EVERETT-UPRR #1
API: 05-039-06428



Photo 7. Photo taken of the eastern well location on November 3, 2017, facing East. Operator has not reclaimed the location per Rule 1004 standards. The location has not been contoured to match the surrounding landscape. Rill erosion evident along the eastern cut slope.



Photo 8. Photo taken of the eastern well location on April 20, 2018, facing East. Operator has failed to complete final reclamation activities.

Inspection Photos
Location Name: RMPCO-EVERETT-UPRR #1
API: 05-039-06428



Photo 9. Photo taken from the western battery location on 3/12/2020, facing West. Photo illustrates Operator has failed to conduct any of previous corrective actions- refer to Photos 3-6.



Photo 10. Photo taken from the western battery location on 3/12/2020, facing West. See comments under Photo 9.

Inspection Photos
Location Name: RMPCO-EVERETT-UPRR #1
API: 05-039-06428



Photo 11. Photo taken of the eastern well location on 3/12/2020, facing Northeast. Photo illustrates Operator has failed to conduct any of previous corrective actions- refer to Photos 7-8.



Photo 12. Photo taken of the southeastern well location on 3/12/2020, facing East. See comments under Photo 11.