

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/12/2020

Submitted Date:

03/13/2020

Document Number:

688307279**FIELD INSPECTION FORM**Loc ID 322209 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10646Name of Operator: AXIS EXPLORATION LLCAddress: 370 17TH ST SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Antonioli, Philip	720-345-4603	PAntonioli@extractionog.com	
Dunning, Michael	303 396-6040	mdunning@extractionog.com	
Extraction	720-370-5540	COGCCInspections@extracti onog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209725	WELL	SI	04/01/2018	GW	039-06630	HSR-WHITEHEAD 14-9	PA

General Comment:

PA Inspection

Inspector and rig on location on 3/12/2020. Hot oiler required. Will set bottom CIBP on 3/13/2020 and pump 65 sxs cement (Inspector did not witness due to back weather).

Inspected Facilities									
Facility ID:	209725	Type:	WELL	API Number:	039-06630	Status:	SI	Insp. Status:	PA
Workover									
Comment: <div>Ensign Rig on location pulling rods and tubing, hot oil needed.</div>									
Corrective Action: <div></div> Date: <div></div>									