

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/28/2020

Submitted Date:

03/09/2020

Document Number:

698100130

FIELD INSPECTION FORM

Loc ID 335618 Inspector Name: Arauza, Steven On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
8 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Middleton, Brett		bmiddleton@caerusoilandgas.com	Sr. Environmental Specialist
Heil, John		john.heil@state.co.us	
Janicek, Jake		JJanicek@caerusoilandgas.com	EHS Professional
Fischer, Alex		alex.fischer@state.co.us	
,		COGCC.inspections@caerusoilandgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287572	WELL	PR	03/01/2019	GW	045-13001	UNOCAL-ENCANA 23D-4D	EI
288397	WELL	PR	03/01/2019	GW	045-13237	UNOCAL-ENCANA 24B-4D	EI
288398	WELL	PR	03/01/2019	GW	045-13236	UNOCAL-ENCANA 23B-4D	EI
288399	WELL	PR	03/01/2019	GW	045-13235	UNOCAL-ENCANA 24A-4D	EI
288400	WELL	PR	03/01/2019	GW	045-13234	UNOCAL-ENCANA 23A-4D	EI
439130	CENTRALIZED EP WASTE MGMT FAC	AL	05/30/2018		-	VALLEY TRANSFER FACILITY 439130	EI
444666	NONFACILITY	AC	02/02/2016		-	UNOCAL-ENCANA-66S96W "Unocal 5" 335618	EI

General Comment:

COGCC Environmental Inspection. Follow-up to operator's Cuttings Waste Management Plan (doc #402308673). Weather conditions during inspection were sunny with a temperature of 31 degrees Fahrenheit. Facility was partially covered with snow and ice on inspection date.

Operator's Waste Management and Beneficial Reuse Plan (doc #402308676) describes operator's intention to stockpile surface cuttings from an adjacent pad in the southwest corner of this location.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

DEBRIS

Comment: Tank battery liner debris (felt and mesh material scraps) located in former tank battery area on west side of pad. See photos.

Corrective Action: Comply with Rule 603.f.

Date: 03/24/2020

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		Adequate
Comment: Localized accumulations of snow and ice in secondary containment area. No holes or tears were observed in visible portions of tank battery liner on inspection date. See photos.				
Corrective Action: <input type="text"/>				Date: <input type="text"/>

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 287572 Type: WELL API Number: 045-13001 Status: PR Insp. Status: EI

Facility ID: 288397 Type: WELL API Number: 045-13237 Status: PR Insp. Status: EI

Facility ID: 288398 Type: WELL API Number: 045-13236 Status: PR Insp. Status: EI

Facility ID: 288399 Type: WELL API Number: 045-13235 Status: PR Insp. Status: EI

Facility ID: 288400 Type: WELL API Number: 045-13234 Status: PR Insp. Status: EI

Facility ID: 439130 Type: CENTRALIZE API Number: - Status: AL Insp. Status: EI

Facility ID: 444666 Type: NONFACILIT API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Operation of SVE system located west of tank battery documented under Remediation Project #9489. Operator's eForm 27 (doc #2211269) was approved with a COA instructing operator to "resubmit the October 2013 proposal for long term MNA (referenced in the attached Project Summary)." As of 3/9/2020, the referenced MNA proposal has not been uploaded to the COGCC database.

Corrective Action: Operator shall provide a project update to the COGCC via a Supplemental eForm 27. Operator's eForm 27 shall include the MNA proposal as an attachment, per COAs on doc #2211269. Date: 04/23/2020

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: Operator has submitted a Supplemental eForm 27 (doc #402334419) as an update with closure request to Remediation Project #15065. The update is currently under review by the COGCC.

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402336287	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5088965
698100139	20200228 field photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5088964