

Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Aerial Photo, provided to give context to photos. Berm west of tanks separates the tank battery from lower level secondary containment.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #1 tank battery sign. Hydrocarbon impacts on sign.

Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #2 Chemicals at tank battery.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #3 Chemicals at tank battery

Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #4 upper portion of tank battery. Note: staining on tank  
this tank overtopped.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #5 photo taken looking west. Tank in photo is the south end of the tank battery.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #6 looking north. Tank overtopped.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #7 Pooled Oil in the lower level secondary containment.

Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #8 looking northwest at lower level of secondary containment. It is hard to see in this photo, soils were surface scraped to push oil to the south-west corner for vacing.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #9 Water truck vacing up oil/water.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #10 camera is sanding in lower level secondary containment. Looking southeast.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #11 Camera is inside of lower level secondary containment, looking at tank battery level.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel

Photo #12 Camera is inside of lower level secondary containment, looking at tank battery level.

Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #13 Pooled oil from tank battery level. This is where oil transferred to the lower level of the secondary containment, note black soil at lower right of photo.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #14 Area where spill flowed from upper tank battery to lower level secondary containment.



Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel

Photo #15 spill flowed from left of photo to western berm of the lower level secondary containment. Spilled fluid was pushed to the southwest side of the containment area for vacing.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Spill Fac ID 473059  
Inspection Date: 3/10/2020  
All Photos taken by Kris Neidel



Photo #16 cattle guard on county Rd 8. COGCC notified KPK staff and Jackson County Road and Bridge. R&B was headed out from the shop to mark the cattle guard for safety prior to repair.

