



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

**Equipment:**

					corrective date
Type: Bradenhead	# 1				
Comment:	Appears to be plumbed to surface				
Corrective Action:		Date:			
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:		Date:			

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 244557 Type: WELL API Number: 123-12352 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary  On (3/17/2020) at approximately (1:40 PM), I, Inspector (Abe Serna),  Conducted an on-site inspection at (Rice #22-1) (PDC Energy), at  (Location #322971) in (Weld County) Colorado.  While there, I observed (PR Well)  During this inspection no compliance issues were observed.  No follow up on this site inspection needs to be conducted.  This is a summary of inspection report.  Continuing Inspector Training.</p>	sernaa	03/17/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698701185	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5098757">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5098757</a>