



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	stained soil below flow line see pic 1 and pic 2		
Corrective Action:	Comply with 603.f	Date:	04/16/2020
Type	OTHER		
Comment:	Mechanical issue see pic 1 and 2		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	04/16/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Red AG fencing		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 260530 Type: WELL API Number: 001-09438 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On 3/16/20 at approximately 1000 I, Inspector Justin Medina conducted an on-site inspection at Petroshare- API 001-09438 Sterkel 21-1 in Adams County Colorado. While there, I observed Shut in well                      This is a follow up inspection from document # 687400739.                      Corrective actions from previous inspection appear to have been addressed.                      During this inspection the following possible compliance issues were observed:                      Stained soil below flow line see pic 1 and pic 2                      Comply with 603.f 4/16/20                      Mechanical issue see pic 1 and 2                      Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 4/16/20                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      At time of inspection perception of location may have been distorted due to weather conditions.                      This is a summary of inspection report.</p>	medinaj	03/16/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500958	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5098862">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5098862</a>